



Pursuit Platinum and Pursuit 2020 Limited

Air conditioner update

We have been made aware that some customers are experiencing a lack of cooling power with their **Truma Saphir AC unit**. This issue should only be affecting customers with post 1/1/2020 Pursuit models.

We have found a solution which involves installing an extra air return vent in the main cabin, adding a removable cover to the internal pole hole and adding a third air outlet. This will sufficiently solve any issues you may have been facing and effectively enhance the performance of the AC unit. The kits will be available early in 2022 and can be installed by the handy DIY customer or we can organise to install and our Redhead factory or registered caravan repair agent.

Please make contact via [BRS offroad enquiries](#) if you have concerns or to make a booking.